

MEMORANDUM FOR RECORD

SUBJECT: Fort Gibson Lake, OK; Pryor Creek Concession; Recreational Lease
DACW56-1-08-266; On-Site Environmental Inspection

DATE: 05 Apr 2016

1. Accompanied Oklahoma Department of Environmental Quality (DEQ) during on-site inspection of lease area, as requested by lessees Carolyn Sinor and Eddie Sinor. In attendance with Robin Stratton and Robert Huber, DEQ Environmental Programs Specialists, (b)(6) USACE Employee Info, US Army Corps of Engineers Environmental Specialist, and (b)(6) USACE Employee Info, US Army Corps of Engineers Field Realty Specialist.
2. On-site inspection found as follows:
 - a. Evidence of faulty wiring, electric panels electrical and evidence of raw sewage at the upper lift station area.
 - b. Inadequate wiring, plumbing, and evidence of raw sewage on the ground at the lower lift station.
 - c. Raw sewage spewing from the air relief valve south of the lower lift station.
 - d. No evidence of working lateral lines were located on the lease area.
 - e. Hazardous waste dump on the south end of lease area.
3. Meeting was held Carolyn Sinor and Eddie Sinor at conclusion of site inspection to advise of the findings. Mr. and Ms. Sinor contend someone had turned off the pump stations and that there is no raw sewage coming from the upper lift station. Ms. and Mrs. Sinor were advised by Mr. Huber that they would be reporting the findings from today's inspection to their supervisor.

(b)(6) USACE Employee Info

Field Realty Specialist






















TANK ALERT[®]
Alarm System

WARNING



LIGHT



HORN



SILENT

HIGH LIQUID LEVEL ALARM

A4-2

GOULDS PUMPS, INC.
WATER SYSTEMS DIVISION

TO TEST



PUSH

TANK ALERT[®]
Alarm System

WARNING



LIGHT



HORN



SILENT

HIGH LIQUID LEVEL ALARM

A4-2

 **GOULDS PUMPS, INC.**
WATER SYSTEMS DIVISION

TO TEST



PUSH

























