

Changes proposed by the Corps of Engineers
to the current
Shoreline Management Plan
for
Tenkiller Lake (1996)

Cove Densities: (See paragraph 4-02.a.) Change to read:
Existing docks, in areas of greater than 50% density, that
require replacement of substructure will not be allowed to
be rebuilt at the same location. The dock owner may
construct a new dock in an area that is zoned for limited
development and has less than 50% density.

Section V, Implementation: (5-01. General) Add the
following statement: Floating facilities may not be moved
to other locations without written permission from the Lake
Manager. The fee for new docks and renewals is \$30.00 for a
5-year permit.